

Video System Mapping Problem

AFFECTED: SD4HW, SD4HC
As well as their Reseller Designation versions

Please note:
Unlike some other solutions providers who hide their flaws and hardware/software issues, we prefer to operate in an honest open manor that respects a customers right to know what they are getting and any problems & solutions


FIELD SERVICE MEMO #40

Issue Date
March 1, 2019

American Bus Video Inc.

2545 Valley Ridge Dr.
Cumming, GA. 30040
Toll Free 866-468-8042
770-887-5944 Fax

www.AmericanBusVideo.com

Topic	Video System Mapping Problem
Problem	Customers have noticed map display problems with the AVPlayer software
Customer Error Message	
Google Mapping Changes	Google is the map program of choice for many mobile DVR software products. When Google makes changes in their mapping program, that improve their product function on occasion this adversely affects those mobile video software programs using the product.
Manufacturer Notice	On February 28, 2019 we made the manufacturer aware of the problem. We tested several other manufacturer products that also demonstrated the same problem.
Manufacturer Action Taken	Within 12 hours of the reported problem, ABV received a corrected DVR_Player version software program, that was tested and mapping function verified to properly function.
Customers Recommended Actions	At this time we are recommending all customers Update Software to "DVR_Player setup V2.37.19.15 EN" New DVR_Player Software available for free download at: https://americanbusvideo.com/CUSTOMER-FTP/SD4HD.%20SD4HW%20&%20SD4HC/Video%20Playback%20Software/DVR_Player%20setup%20V2.37.19.15%20EN/